

Coordinates

| 10/28: 3375 x 60 (ASPH-G) | | Latitude Longitude | 43-14-05.000N 077-07-15.500W |
|------------------------------------|---|--|---------------------------------|
| Communications | | Navigation | |
| CTAF/U | · · - | Elevation | 425 03 W |
| PCL | 122.8 | NM from City Instr Approach | GPS RUNWAY 28 |
| Owner/Manager | | Services | |
| Owner Manager | WILLIAMSON FLYING CLUB INC MR LANCE MERRITT PO BOX 148 | Fuel Airframe Repairs Engine | 100LL 80 MAJOR MAJOR |
| Phone Fax E-mail Web site | WILLIAMSON NY 14589 (315) 483-6011 Airport # (315) 483-7296 | Attended Airline Airport Transportation Food Lodging | ALL/MON-FRI/0830-1700 NO |

FBO (Location)

Runways

WILLIAMSON AERONAUTICAL SERVICE (315) 483-8934 DEAN'S AERO SERVICE (315) 483-2067 WILLIAMSON FLYING CLUB INC (315) 483-6011

Remarks

100 LL AND 80 AVAILABLE BY CREDIT CARD SELF SERVE 24 HOURS A DAY. AREAS OTHER THAN RWYS OR TWYS MAY BE VERY SOFT IN SPRING, FALL & WINTER.